BORDER SAFETY WEARS

PRODUCT DATASHEET

NO BURN COVERALL

Product Code: TFRC 2000

Coverall | EN ISO 11611 | EN ISO 11612

S - 6XL











PRODUCT DESCRIPTION

The No Burn Coverall is made from 100% cotton flame-retardant fabric at 200-220 GSM, permanently treated for flame resistance and certified to EN ISO 11611:2015 and EN ISO 11612:2015. It closes with a two-way zipper and stud button, and features 2 chest pockets with flap cover, a sleeve pen pocket, 2 side cross pockets, 2 back hip pockets, an elasticated waist round belt, and 2" reflective tape at 6 spots. Available in Royal Blue and Red.

TECHNICAL SPECIFICATIONS

Standard	EN ISO 11611:2015, EN ISO 11612:2015
Fabric Composition	100% Cotton Flame Retardant
Weight/GSM	200-220 GSM
Colour	Royal Blue, Red
Closure	Two-way zipper with stud button
Pockets	2 chest pockets with flap cover, 1 sleeve pen pocket, 2 side cross pockets, 2 back hip pockets
Reflective Tape	2" tape in 6 spots
Additional Features	Elasticized waist round belt, triple-stitched seams, fully bar-tacked stress points
Sizes	S-6XL
Origin	PRC

BORDER®
SAFETY WEARS

KEY FEATURES

- 100% cotton flame-retardant fabric, 200-220 GSM
- Certified EN ISO 11611 & 11612
- Two-way zipper with stud closure
- Triple-stitched, fully bar-tacked
- 2" reflective tape in 6 spots
- Suited for foundries, welding & electrical work

PROTECTIVE FEATURES

EN ISO 11611:2015 (Welding)	Protects against welding spatter and radiant heat
EN ISO 11612:2015 (Heat & Flame)	Protects against limited flame spread and convective heat
Flame Retardant Treatment	Permanent flame resistance for the life of the garment
Reflective Tape (2" in 6 spots)	Improves visibility in low light

CERTIFICATIONS

- EN ISO 11611:2015 :: Certifies protective clothing for welding and allied processes with related risks such as spatter and radiant heat
- EN ISO 11612:2015 :: Certifies clothing that protects against heat and flame; the garment is flame-resistant, not fireproof

INDUSTRIES

- Foundries
- Flame Cutting
- Welding
- Electric Utilities

WASH CARE GUIDE

- Wash promptly if contaminated with oil, fuel, chemicals or other flammable substances.
- Use a mild detergent; avoid bleach, fabric softener and starch.
- Do not tumble dry - allow the garment to air-dry without excessive heat.
- Inspect after every wash for holes, thinning, broken seams or peeling reflective tape.