BORDER SAFETY WEARS

PRODUCT DATASHEET

BFP2064

Product Code: BFP 2064

Safety Shoe | EN ISO 20345:2022 | S3 SR FO HRO LG

Sizes: EU 38-47











AREA OF APPLICATION

Recommended for construction, oil & gas, manufacturing and heavy industrial environments where impact, puncture, slip, water, fuel-oil and contact-heat protection is required.

TECHNICAL SPECIFICATIONS

Safety Category	S3 SR FO HRO LG
Upper Material	Genuine Leather
Lining	Highly Abrasion-Resistant Fabric
Toe Cap	Epoxy-Coated Steel Toe Cap (200 Joules)
Midsole	Epoxy-Coated Steel Plate (1100N Puncture Resistance)
Collar	Padded Collar Under the Tongue
Insole	Removable Antistatic Fabric-Lined
Outsole	Dual-Density (Heat Resistant to 300 C)
Visibility	Integrated High-Visibility Stripes
Colour	Black
Origin	China

KEY FEATURES

- EN ISO 20345:2022 Certified
- 200J Steel Toe Cap
- 1100N Steel Puncture-Resistant Midsole

BORDER®
SAFETY WEARS

- Water-Resistant Genuine Leather Upper (S3)
- Dual-Density Heat-Resistant Outsole (300 C)
- Integrated High-Visibility Stripes
- Slip Resistant (SR)
- Fuel Oil Resistant (FO)
- Heat Resistant Outsole (HRO)
- Ladder Grip (LG)
- Antistatic

PROTECTIVE FEATURES

Steel Toe Cap (200J)	Protection against impact and compression hazards.
Steel Midsole (1100N)	Puncture resistance against sharp objects.
Water-Resistant Upper (WPA)	Protects against water penetration and absorption.
Slip Resistant Outsole (SR)	Reliable grip on industrial flooring.
Fuel Oil Resistant Sole (FO)	Resistant to degradation from fuel oil exposure.
Heat Resistant Outsole (HRO)	Withstands contact heat up to 300 C.
Ladder Grip (LG)	Enhanced stability when working on ladders.
Antistatic	Dissipates static charge build-up.
Shock Absorption	Reduces impact stress in the heel area.

CERTIFICATIONS

- EN ISO 20345:2022
- S3 SR FO HRO LG
- CE Marked

S3	200J toe, steel puncture-resistant midsole & water-resistant upper.
SR	Slip resistance.
FO	Fuel oil resistant outsole.
HRO	Heat resistant outsole to 300 C.
LG	Ladder grip outsole.

INDUSTRIES

- Construction
- Oil & Gas

- Manufacturing
- Logistics
- Warehousing
- Engineering
- Maintenance

STORAGE & MAINTENANCE

- Store in a cool and dry location.
- Avoid prolonged exposure to direct sunlight.
- Clean with a soft brush or damp cloth.
- Do not use strong solvents or harsh chemicals.
- Allow footwear to dry naturally after use.
- Replace footwear if excessive wear or damage is observed.

WARRANTY

6 MONTHS MANUFACTURING WARRANTY. Warranty covers manufacturing defects under normal working conditions. Warranty is void if products are subjected to excessive heat, chemicals, cement water, bleach or water.